


SZIV

Suction strainer with male and female ends for solvent welding to foot valve VZ



Objednáací číslo	Materiál	Kategorie	d	product.detail.attribute.d[5:1]	DN
SZIV016	FLS Measurement Instrumentation	Příslušenství k ručním armatury	16	16	10
SZIV020	FLS Measurement Instrumentation	Příslušenství k ručním armatury	20	20	15
SZIV025	FLS Measurement Instrumentation	Příslušenství k ručním armatury	25	25	20
SZIV032	FLS Measurement Instrumentation	Příslušenství k ručním armatury	32	32	25
SZIV040	FLS Measurement Instrumentation	Příslušenství k ručním armatury	40	40	32
SZIV050	FLS Measurement Instrumentation	Příslušenství k ručním armatury	50	50	40
SZIV063	FLS Measurement Instrumentation	Příslušenství k ručním armatury	63	63	50

- Upper part (PVC-U)
 - Bottom part (PVC-U)
 - Bolts (zinc plated steel)
 - Nuts (zinc plated steel)
 - Gasket (NBR)
 - Reinforcing ring (Stainless steel)
- The reinforcing bush are used to reinforce the pipe PE100 (SDR11) e PE-X, to elong the lifetime of the pipeline and to reduce the collapse risk of the pipe in disadvantages conditions. They use is particularly suggested using PE-X pipes. The two tightening keys (d.16-63 and d.75-110) are important tools to install the **MAGNUM 3G** fittings