

DIV

Reducing bush with solvent weld spigot (d) and solvent weld socket (d1 reduced) (fig. B)




Fig. B